

## Technical Service Bulletin

<b>Reference:</b> ICOM-TSB15-003	<b>Date:</b> 5/20/2015
-------------------------------------	---------------------------

### Regulator and Supply Solenoid Installation

**UNITS AFFECTED:**

New or current installations of the JTG II Bi Fuel Liquid Propane System.

**SERVICE INFORMATION:**

This bulletin provides installation location information for the regulator and supply solenoid assemblies inside the engine compartment.

**PURPOSE**

To eliminate the possibility of a noise/vibration to transmit into the passenger compartment of the vehicle.

**ACTION:**

Verify that the regulator and/or supply solenoid is not mounted to the dash panel inside the engine compartment as this will cause a noise/vibration to transmit into the passenger compartment when the propane system is on. If this is the case, reinstall the regulator and/or supply solenoid at a location somewhere on the engine or to the inner fender panel (see Attachment 'A' for example locations). Contact the ICOM technical department if further assistance is required.

